

**84\*/2023            MALAYSIA – Sarawak – Tanjung Po – Buoy.**

**Source: Sarawak Marine Department No. 75,76/2023.**

1. Buoy No. 2, *Fl.R.5s*, 01°48'.17N, 110°30'.98E and Buoy No. 4, *Fl.R.5s*, 01°45'.25N, 110°32'.13E is restored to normal.
  2. Former Notice No. 52(T)\*/23 and 56(T)\*/23 is cancelled.  
(WGS84)
  3. Charts affected – MAL 7150.
- .....