

224*/2023 MALAYSIA – Sarawak – Kuala Rajang – Buoy.

Source: Sarawak Marine Department No. 172(T)/2023.

1. Isolated Danger Mark Buoy, *Fl(2)6s*, in position 02°07'.49N, 111°06'.56E is restored to normal.
 2. Former Notice No. 53(T)*/23 is cancelled.
(WGS84)
 3. Charts affected – MAL 7215.
-