

53(T)*/2023 MALAYSIA – Sarawak – Kuala Rajang – Buoy.

Source: Sarawak Marine Department No. 45(T)/2023.

1. Isolated Danger Mark Buoy, *Fl(2)6s*, in position 02°07'.49N, 111°06'.56E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7215
-