

**53(T)\*/2023      MALAYSIA – Sarawak – Kuala Rajang – Buoy.**

**Source: Sarawak Marine Department No. 45(T)/2023.**

1. Isolated Danger Mark Buoy, *Fl(2)6s*, in position 02°07'.49N, 111°06'.56E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 7257
-