

37(T)*2024 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 7(T)/2024.

1. Buoy No. 6, *F.R.5s*, in position 03°15'.95N, 113°01'.23E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7317.
-