

**75(T)\*/2021 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.**

**Source: Sarawak Marine Department No. 25/2021(T).**

1. Buoy K *Fl.G.5s*, in position 03°15'.14N, 113°02'.55E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 7317.
-