

**80(T)\*/2022 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.**

**Source: Sarawak Marine Department No. 66/2022(T).**

1. Buoy Y5 *Fl. Y.5s*, in position 03°15'.97N, 113°03'.84E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 7317
-