

**69(T)\*/2024      MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.**

**Source: Sarawak Marine Department No. 31(T)/2024.**

1. No. 11 buoy, *Fl.G.5s*, in position 03°15'.52N, 113°02'.57E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 7332.
-