

MAL 7332

88/2008*(T) Malaysia – Sarawak – Bintulu Port – Inner Harbour – Beacon.

Source : Sarawak Marine Department 37/2008(T).

Chart MAL 7332 (Last Correction 193/2007) REVISED TIMBALAI 1948 DATUM

Insert legend, (*Unlit*) for
Beacon, Bintulu Port Oc.R.5s 03° 15'. 70N, 113° 04'. 26E

122/2008* Malaysia – Sarawak – Kuala Kemena – Beacon.

Source : Sarawak Marine Department 59/2008(T).

Chart MAL 7332 (Last Correction 88(T)/2008) WGS 84 DATUM

Insert legend, (***Unlit***) for
Kuala Kemena, Beacon B11 03° 12'. 01N, 113° 02'. 17E

164/2008* Malaysia – Sarawak – Bintulu North – Eastwards – Kuala Tatua Eastwards – Wrecks .

Source : British Admiralty Notices No. 0936/2005.

Chart MAL 7332 (Last Correction 122/2008) WGS 84 DATUM

Insert  (a) 3° 10'. 52N, 112° 59'. 08E

Delete  ,close NE of: (a) above

184/2008*(T) Malaysia – Sarawak – Bintulu Port Access Channel – Light – Out Of Service.

Source : Sarawak Marine Department 91/2008.

Chart MAL 7332 (Last Correction 164/2008) WGS 84 DATUM

Insert legend, (***Out Of Service***) for
Leading Light, Bintulu Port 102 B Iso.9s13m 03° 14'. 60N, 113° 04'. 67E

185/2008*(T) Malaysia – Sarawak – Bintulu Port – Inner Harbour – Beacon.

Source : Sarawak Marine Department 92/2008.

Chart MAL 7332 (Last Correction 184/2008) WGS 84 DATUM

Beacon J5, Bintulu Port Oc.R.5s 03° 15'. 66N, 113° 04'. 46E

Former Notice 88/2008 is cancelled

43/2009*(T) Malaysia – Sarawak – Bintulu – Fairway Buoy.

Source : Sarawak Marine Department No. 5/2009(T).

Chart MAL 7332 (Last Correction 185(T)/2008) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for Kuala Kemena, Bintulu, <i>Fairway Fl.R.4s</i>	03° 11'. 54N,	113° 00'. 42E
--------	---	---------------	---------------

44/2009*(T) Malaysia – Sarawak – Pelabuhan Bintulu – Buoys.

Source : Sarawak Marine Department No. 6/2009(T).

Chart MAL 7332 (Last Correction 28/2009) WGS 84 DATUM

Insert	legend,(Missing) for Buoy No. 5, Fl.G.5s	03° 15'. 82N,	113° 01'. 21E
Insert	legend,(Missing) for Buoy 'G', Fl.G.5s	03° 15'. 34N,	113° 01'. 68E
Insert	legend,(Missing) for Buoy 'L', Fl.R.5s	03° 15'. 29N,	113° 02'. 62E

.....
61/2009*(T) Malaysia – Sarawak – Bintulu Port – South Access Channel – Buoy Missing.

Source : Sarawak Marine Department No. 12/2009(T).

Chart MAL 7332 (Last Correction 44(T)/2009) WGS 84 DATUM

Insert	legend, (Missing) for Buoy J Fl.R.5s	03° 15'. 36N,	113° 02'. 27E
---------------	--	---------------	---------------

.....
62/2009* Malaysia – Sarawak – Kuala Bintulu – Wreck.

Source : Sarawak Marine Department No. 09/2009.

Chart MAL 7332 (Last Correction 61(T)/2009) WGS 84 DATUM

Insert		03° 13'. 20N,	113° 58'. 50E
---------------	--	---------------	---------------

.....
120/2009*(T) Malaysia – Sarawak – Bintulu Port – South Access Channel – Buoy Unlit.

Source : Sarawak Marine Department No. 41/2009(T).

Chart MAL 7332 (Last Correction 62/2009) WGS 84 DATUM

Insert	legend, (Unlit) for Buoy F, Fl.R.5s	03° 15'. 55N,	113° 01'. 16E
---------------	---	---------------	---------------

.....
121/2009*(T) Malaysia – Sarawak – Bintulu Port – South Access Channel – Resumed Operation.

Source : Sarawak Marine Department No. 42/2009(T).

Chart MAL 7332 (Last Correction 117/2009 (T)) WGS 84 DATUM

Buoy J, Fl.R.5s	03° 15'. 36N,	113° 02'. 27E
Buoy L, Fl.R.5s	03° 15'. 29N,	113° 02'. 62E
Buoy G, Fl.G.5s	03° 15'. 34N,	113° 01'. 67E
Buoy No.5, Fl.G.5s	03° 15'. 82N,	113° 01'. 21E
Notice No. 61/2009(T) and Notice No. 44/2009(T) is hereby cancelled		

.....

173/2009*(T) Malaysia – Sarawak – Bintulu Port – South Access Channel – Buoy.

Source : Sarawak Marine Department No. 76/2009(T).

Chart MAL 7332 (Last Correction 121/2009(T)) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for <i>Buoy H, Fl.R.5s</i>	03° 15'. 46N,	113° 01'.70E
---------------	--	---------------	--------------

186/2009*(T) Malaysia – Sarawak – Pelabuhan Bintulu – Buoy.

Source : Sarawak Marine Department No. 84/2009(T).

Chart MAL 7332 (Last Correction 173/2009) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for <i>Buoy I, Fl.G.5s</i>	03° 15'. 24N,	113° 02'. 26E
---------------	--	---------------	---------------

65/2010*(T) Malaysia – Sarawak – Bintulu Port – Buoy.

Source: Sarawak Marine Department No. 14/2010(T).

Chart MAL 7332 (Last Correction 186/2009(T)) 2010) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for <i>Buoy 'K', Fl.G.5s</i>	03° 15'. 19N,	113° 02'. 52E
---------------	--	---------------	---------------

66/2010* Malaysia – Sarawak – Bintulu Port – South Access Channel – Kuala Kemena – Buoy – Resumed Operation.

Source: Sarawak Marine Department No. 16/2010.

Chart MAL 7332 (Last Correction 62/2010) WGS 84 DATUM

<i>Buoy H, Fl.R.5s</i> Notice No. 173/2009(T) is hereby cancelled.	03° 15'. 46N,	113° 01'.70E
---	---------------	--------------

<i>Buoy I, Fl.G.5s</i> Notice No. 186/2009(T) is hereby cancelled.	03° 15'. 24N,	113° 02'. 26E
---	---------------	---------------

<i>Buoy F, Fl.R.5s</i> Notice No. 120/2009(T) is hereby cancelled.	03° 15'. 55N,	113° 01'. 17E
---	---------------	---------------

Kuala Kemena, Bintulu, <i>Fairway Fl.R.4s</i> Notice No. 43/2009(T) is hereby cancelled.	03° 11'. 54N,	113° 00'. 42E
---	---------------	---------------

85/2010* Malaysia – Sarawak – Bintulu Port – South Access Channel – Buoy – Resumed Operation.

Source: Sarawak Marine Department No. 28/2010.

Chart MAL 7332 (Last Correction 66(T)/2010) WGS 84 DATUM

<i>Buoy K, Fl.G.5s</i> Notice No. 65/2010(T) is hereby cancelled.	03° 15'. 19N,	113° 02'.52E
--	---------------	--------------

109/2010* Malaysia – Sarawak Water – Kuala Bintulu – Wreck Beacon.

Source: Sarawak Marine Department Notice No. 35/2010.

Chart MAL 7332 (Last Correction 85/2010) WGS 84 DATUM

Insert	 <i>Wesonic 8</i> <i>Fl(2)10s</i>	03° 11'.01N,	113° 01'.29E
---------------	---	--------------	--------------

190/2010* Malaysia – Sarawak – Kuala Bintulu – Buoys.

Source: Sarawak Marine Department No. 59/2010.

Chart MAL 7332 (Last Correction 109/2010) WGS 84 DATUM

Insert	 <i>Fl.R.4s</i>	03° 11'.09N,	113° 01'.27E
	 <i>Fl.G.4s</i>	03° 11'.11N,	113° 01'.66E

40/2011(T)* Malaysia – Sarawak Water – Kuala Bintulu – Wreck Beacon Collapsed.

Source: Sarawak Marine Department Notice No. 3/2011(T).

Chart MAL 7332 (Last Correction 190/2010) WGS 84 DATUM

Insert	legend, (Collapsed) for ‘Wesonic 8’ Wreck beacon, Fl(2)10s	03° 11'.01N,	113° 01'.28E
--------	--	--------------	--------------

77/2011* South China Sea – Malaysia – Oil Field Bintulu – Platforms.

Source: Sarawak Marine Department No. 27/2011.

Chart MAL 7332 (Last Correction 40/2011(T)) WGS 84 DATUM

Insert	 TRUNKLINE A	03° 17'.51N,	113° 04'.77E
	 TRUNKLINE B	03° 17'.51N,	113° 04'.76E

82/2011(T)* Malaysia – Sarawak – Kuala Bintulu – Buoy Missing.

Source: Sarawak Marine Department Notice No. 23/2011(T).

Chart MAL 7332 (Last Correction 77/2011) WGS 84 DATUM

Insert	legend, (Missing) for Kuala Kemena, Porthand Buoy, <i>Fl.R.4s</i>	03° 11'.09N,	113° 01'.27E
--------	---	--------------	--------------

157/2011* Malaysia – Sarawak – Bintulu Port – South Access Channel – Kuala Kemena – Buoy.

Source: Sarawak Marine Department No. 59/2011.

Chart MAL 7332 (Last Correction 82/2011(T)) WGS 84 DATUM

Insert	 <i>Fairway Fl.4s</i>	03° 12'.46N,	113° 00'.87E
Delete	 <i>Fairway Fl.R.4s</i>	03° 11'.54N,	113° 00'.42E

206/2011* **Malaysia – Sarawak – Kuala Bintulu – Buoys.**

Source: Sarawak Marine Department No. 80/2011.

Chart MAL 7332 (Last Correction 157/2011) WGS 84 DATUM

Insert	 <i>Fl.R.4s</i>	03° 11'.89N,	113° 01'.36E
Delete	 <i>Fl.R.4s</i>	03° 11'.09N,	113° 01'.27E

44/2012(T)* **Malaysia – Sarawak – Kuala Kemena, Bintulu – Buoy.**

Source: Sarawak Marine Department No. 87/2011(T).

Chart MAL 7332 (Last Correction 206/2011) WGS 84 DATUM

Insert	legend (<i>Missing</i>) for <i>Kuala Kemena buoy, Fl.G.4s</i>	03° 11'.11N,	113° 01'.66E
---------------	--	--------------	--------------

45/2012(T)* **Malaysia – Sarawak – Kuala Kemena Bintulu – Buoy.**

Source: Sarawak Marine Department No. 85/2011(T).

Chart MAL 7332 (Last Correction 44/2012(T)) WGS 84 DATUM

Insert	legend (<i>Missing</i>) for <i>Kuala Kemena buoy, Fl.R.4s</i>	03° 11'.89N,	113° 01'.36E
---------------	--	--------------	--------------

106/2012 **Malaysia – Sarawak – Kuala Bintulu – Buoy.**

Source: Sarawak Marine Department Notice No. 24/2012.

Chart MAL 7332 (Last Correction 45/2012(T)) WGS 84 DATUM

Insert	Kuala Kemena, Porthand Buoy, <i>Fl.R.4s</i> Notice No. 45/2012(T)* is hereby cancelled	03° 11'.89N,	113° 01'.36E
---------------	---	--------------	--------------

115/2013 **Malaysia – Sarawak – Bintulu Port – Kuala Kemena – Bouy Missing.**

Source: Sarawak Marine Department No. 37/2013(T).

Chart MAL 7332 (Last Correction 106/2012) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for <i>Fairway, Fl.R.4s</i>	03° 12'.46N,	113° 00'.87E
---------------	---	--------------	--------------

168/2013 **Malaysia – Sarawak – Bintulu Port – Kuala Kemena – Resumed Operation.**

Source: Sarawak Marine Department No. 96/2013.

Chart MAL 7332 (Last Correction 115/2013) WGS 84 DATUM

Delete	legend, (<i>Missing</i>) for <i>Fairway, Fl.R.4s</i> Notice No. 115/2013(T) is hereby cancelled	03° 12'.46N,	113° 00'.87E
---------------	---	--------------	--------------

196/2013(T) Malaysia – Sarawak – Kuala Kemena – Bintulu – Buoy Missing.

Source: Sarawak Marine Department No. 119/2013(T).

Chart MAL 7332 (Last Correction 168/2013) WGS 84 DATUM

Insert	legend (Missing) for <i>Kuala Kemena buoy, Fl.R.4s</i>	03° 11'.90N, 113° 01'.35E
---------------	--	------------------------------

57/2014 Malaysia - Sarawak - Tanjung Baram to Tanjung Datu - Automatic Identification Systems. Anchorage area. Pilot boarding place.

Source: British Admiralty Notices No. 1251/2014.

Chart MAL 7332 (Last Correction 196/2013(T)) WGS 84 DATUM

Insert	 at light	03° 16'.48N, 113° 04'.03E
---------------	--	------------------------------

59/2014 Malaysia - Sarawak - Kuala Kemena - Bintulu - Resumed Operation.

Source: Sarawak Marine Department No. 25/2014.

Chart MAL 7332 (Last Correction 57/2014) WGS 84 DATUM

Delete	legend (Missing) for <i>Kuala Kemena buoy, Fl.R.4s</i> Notice No. 196/2013(T) is hereby cancelled	03° 11'.90N, 113° 01'.35E
---------------	--	------------------------------

Move	 <i>Fl.R.4s</i> to:	03° 11'.90N, 113° 01'.35E 03° 12'.00N, 113° 01'.59E
-------------	---	--

143/2014(T) Malaysia - Sarawak - Kuala Kemena - Beacon.

Source : Sarawak Marine Department 108/2014(T).

Chart MAL 7332 (Last Correction 59/2014) WGS 84 DATUM

Insert	legend, (Out Of Service) for <i>Kuala Kemena, Beacon Fl.Y.5s B11</i> Notice No. 122/2008(T) is hereby cancelled	03° 11'.01N, 113° 02'.17E
---------------	--	------------------------------

31/2015(T) Malaysia - Sarawak - Bintulu Port - North Access Channel - Buoy Missing.

Source : Sarawak Marine Department No. 5/2015(T).

Chart MAL 7332 (Last Correction 143/2014(T)) WGS 84 DATUM

Insert	legend, (Missing) for <i>Buoy No.6, Fl.R.5s</i>	03° 15'.95N, 113° 01'.23E
---------------	---	------------------------------

79/2015(T) MALAYSIA - Sarawak - Bintulu Port - Kuala Kemena - Missing Bouy.

Source: Sarawak Marine Department No. 42/2015(T).

Chart MAL 7332 (Last Correction 31/2015(T)) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for Fairway, <i>Fl.R.4s</i>	03°12'.46N,	113°00'.87E
---------------	---	-------------	-------------

80/2015 MALAYSIA - Sarawak - Bintulu Port – Resumed In Operation.

Source : Sarawak Marine Department No. 45/2015.

Chart MAL 7332 (Last Correction 79//2015) WGS 84 DATUM

Delete	legend, (<i>Missing</i>) for Buoy No.6, <i>Fl.R.5s</i> Notice No. 31/2015(T) is hereby cancelled	03°15'.95N,	113°01'.23E
---------------	--	-------------	-------------

81/2015 MALAYSIA - Sarawak - Kuala Kemena - Resumed In Operation.

Source : Sarawak Marine Department 47/2015.

Chart MAL 7332 (Last Correction 80/2015) WGS 84 DATUM

Delete	legend, (Out Of Service) for Kuala Kemena, Beacon <i>Fl.Y.5s</i> B11 Notice No. 143/2014(T) is hereby cancelled	03°12'.01N,	113°02'.17E
---------------	--	-------------	-------------

124/2015(T) MALAYSIA – Sarawak – Tg Kidurong – Work in Progress.

Source: Sarawak Marine Department Notice No. 54/2015(T).

Chart MAL 7332 (Last Correction 81/2015) WGS 84 DATUM

Insert	working area for construction of jetty pecked line joining	03° 15'.80N,	113° 03'.06E
		03° 15'.73N,	113°
03'.13E		03° 15'.98N,	113° 03'.39E
		03° 16'.04N,	113° 03'.32E
	legend <i>Works in Progress (2015)</i>	03° 15'.90N,	113° 03'.20E

155/2015(T) MALAYSIA – Sarawak – Pelabuhan Bintulu – Missing Bouy.

Source: Sarawak Marine Department No. 77/2015(T).

Chart MAL 7332 (Last Correction 124/2015) WGS 84 DATUM

Insert	legend, (<i>Missing</i>) for Buoy, <i>No.13 Fl.G.5s</i>	03°15'.37N,	113°02'.83E
---------------	--	-------------	-------------

188/2015 MALAYSIA – Sarawak – Pelabuhan Bintulu – South Access Channel – Resumed in Operation.

Source : Sarawak Marine Department No. 92/2015*.

Chart MAL 7332 (Last Correction 155/2015) WGS 84 DATUM

Delete legend, (*Missing*) for
Buoy No.13, *Fl.G.5s*
Notice No. 155/2015(T) is hereby cancelled 03°15'.37N, 113°02'.83E.

202/2015 MALAYSIA – Sarawak – Tanjung Patong, Tanjung Sirik, Tanjung Sirik(i), Batuan Likau and Kuala Baram – Light Beacon .

Source : Sarawak Marine Department No. 102/2015*.

Chart MAL 7332 (Last Correction 188/2015) WGS 84 DATUM

Insert  Fl. Y. 5s 12m 5M 03° 22'.13N, 113° 07'.94E

36/2016(T) MALAYSIA – Sarawak – Kuala Kemena – Bintulu – Buoy.

Source: Sarawak Marine Department No. 116/2015(T).

Chart MAL 7332 (Last Correction 202/2015) WGS 84 DATUM

Insert legend (*Missing*) for
Kuala Kemena buoy, Fl.R.4s 03° 11'.99N, 113° 01'.59E

112/2016* MALAYSIA – Sarawak – Blocks.

Source: National Hydrographic Centre.

Chart MAL 7332 (Last Correction 36/2016) WGS 84 DATUM

Insert the accompanying block amendment to
Centre on: (a) 03° 11'.40N, 113° 00'.90E
(b) 03° 16'.10N, 113° 02'.50E

115/2016 MALAYSIA – Sarawak – Kuala Bintulu – Buoy – Resumed In Operation.

Source: Sarawak Marine Department No. 39/2016*.

Chart MAL 7332 (Last Correction 112/2016) WGS 84 DATUM

Delete legend (*Missing*) for *Buoy, Fl.G.4s*
Notice No. 44/2012(T) is hereby cancelled 03°11'.11N, 113°01'.66E

197/2016 MALAYSIA – Sarawak – Kuala Kemena – Beacon.

Source: Sarawak Marine Department No. 88/2016*.

Chart MAL 7332 (Last Correction 115/2016) WGS 84 DATUM

Insert legend (*DISUSED*) for
Kuala Kemena Beacon, *Fl.G.12m6M* 03° 11'.19N, 113° 02'.01E

legend (**DISUSED**) for
Kuala Kemena Beacon, Fl.G.21m6M

03° 11'.17N, 113° 02'.07E

Insert  Fl.8s

03° 11'.16N, 113° 02'.05E

219/2016* MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: National Hydrographic Centre.

Chart MAL 7332 (Last Correction 197/2016) WGS 84 DATUM

Insert  Fl.G.5s
'K'

03° 15'.19N, 113° 02'.52E

48/2017* MALAYSIA – Sarawak – Pelabuhan Bintulu – Light beacons.

Source: Sarawak Marine Department No. 19/2017*.

Chart MAL 7332 (Last Correction 219/2016) WGS 84 DATUM)

Amend	light 29A to, Iso.R.12s15M	03° 15'.35N,	113° 04'.35E
	light 29B to, Iso.R.12s18M	03° 15'.25N,	113° 04'.78E
	light 102A to, Iso.Or.6s8m	03° 14'.64N,	113° 04'.54E
	light 102B to, Iso.Or.6s13m	03° 14'.60N,	113° 04'.67E

155/2017 MALAYSIA – Sarawak – Pelabuhan Bintulu – Depth, Light beacon, Wreck,
Light buoy, Racon and Light.

Source: British Admiralty.

Chart MAL 7332 (Last Correction 48/2017) WGS 84 DATUM

Insert  Q.6m8M
BPA

03° 15'.34N, 113° 02'.79E

Replace ++ with 

03° 11'.75N, 113° 01'.44E

 Iso.2s10M
Racon (B)

with

 Iso.2s10m
Racon (B)

03° 16'.38N, 112° 57'.30E

 Fl.G.5s
NO. 12

With

 Fl.R.5s
NO. 12

03° 15'.65N, 113° 02'.99

Amend light to, Fl.G.12s '101A' & Fl.R.3s 'B5'

03° 15'.07N, 113° 03'.49E

159(T)*/2017 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 93/2017(T).

1. The special mark Buoy *F*, *Fl.5s*, in position 03°15'.55N., 113°01'.16E. is reported missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7317 – MAL 7332.
-

175*/2017 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 106*/2017.

1. The special mark Buoy *F*, *Fl.R.5s*, in position 03°15'.55N., 113°01'.16E. is resumed operation.
 2. Former Notice No. 159(T)*/2017 is cancelled.
 3. Charts affected – MAL 7332.
-

223*/2017 MALAYSIA – Sarawak – Pelabuhan Bintulu – Wreck.

Source: Sarawak Marine Department No. 137*/2017.

Chart MAL 7332 (Last Correction 175/2017) WGS 84 DATUM

Insert  *PA* 03° 14'.07N, 113° 03'.14E

229*/2018 MALAYSIA – South China Sea – Kuching-Bintulu – Submarine cable.

Source: Telekom Malaysia Berhad.

Chart MAL 7332 (Last Correction 223/2017) WGS 84 DATUM

Insert submarine cable, , joining: 03° 32'.55N112° 59'.05E(N border)
03° 29'.66N112° 59'.91E
03° 27'.66N113° 00'.80E
03° 25'.92N113° 01'.86E
03° 23'.42N113° 02'.60E
03° 23'.44N113° 03'.82E
03° 20'.37N113° 05'.00E
03° 18'.70N113° 07'.34E(shore)

33*/2018 MALAYSIA – Sarawak – Tg.Similajau – Anchorage areas. Port limits. Geographical Name.

Source: National Hydrographic Centre.


Chart MAL 7332 (Last Correction 29/2018) WGS 84 DATUM

Insert port limit, -----, pecked line, joining: (a) 03° 24'.30N, 113° 10'.19E(E border)
(b) 03° 31'.75N, 113° 02'.26E
(c) 03° 32'.55N, 113° 02'.87E(N border)

55*/2018 MALAYSIA – South China Sea – Bintulu-Miri – Submarine cable.

Source: Telekom Malaysia Berhad.

Chart MAL 7332 (Last Correction 33/2018) WGS 84 DATUM

Insert submarine cable, , joining: 03°18'.70N 113° 07'.35E(shore)
03°20'.94N 113° 05'.19E
03°26'.56N 113° 03'.03E
03°28'.82N 113° 02'.95E
03°32'.55N 113°01'.94E(N border)

159*/2018 MALAYSIA – Sarawak – Kuala Bintulu – Buoy.

Source: Sarawak Marine Department No. *77/2018.

Chart MAL 7332 (Last Correction 55/2018) WGS 84 DATUM

Insert  *Fl.4s*
Fairway 03° 13'.10N, 113° 00'.39E

235(T)*/2018 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 134/2018(T).

1. Pelabuhan Bintulu, Buoy C, *Fl.G.5s*, in position 03°15'.54N, 113°00'.59E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7332.
-

62*/2019 MALAYSIA – Sarawak – Kuala Bintulu – Light buoy.

Source: Sarawak Marine Department No. 17/2019.

Chart MAL 7332 (Last Correction 235/2018) WGS 84 DATUM

Insert  *Fl.R.4s* 03° 11'.36N, 113° 01'.67E

181(T)*/2019 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoys.

Source: Sarawak Marine Department No. 97(T)/2019.

1. Buoy T, *Fl.G.5s*, in position 03°14'.77N, 113°03'.97E and Buoy D, *Fl.R.5s*, in position 03°15'.65N, 113°00'.61E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7332.
-

202*/2019 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoys.

Source: Sarawak Marine Department No. 107(T)/2019.

1. Buoy T, *Fl.G.5s*, in position 03°14'.77N, 113°03'.97E and Buoy D, *Fl.R.5s*, in position 03°15'.65N, 113°00'.61E are resumed in operation.
 2. Former Notice No. 181/2019(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 7332.
-

242*/2019 MALAYSIA – Sarawak – NW Bintulu – Obstruction.

Source: National Hydrographic Centre.

Chart MAL 7332 (Last Correction 202/2019) WGS 84 DATUM

Insert  *Obstn* 01° 12'.61N, 112° 58'.64E

253*/2019

Corrigendum Notices to Mariners 10 of 2019.

Replace Notices No. 242/2019

Chart MAL 7332 (Last Correction 242/2019) WGS 84 DATUM

Insert

9₈

Obstn

03° 12'.61N, 112° 58'.64E

.....
256(T)*/2019 MALAYSIA – Sarawak – Kuala Bintulu – Buoy.

Source: Sarawak Marine Department No. 146(T)/2019.

1. Porthand Buoy Kuala Kemena, *Fl.R.4s*, in position 03°11'.36N, 113°01'.67E is missing.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 7332.

.....
49(T)*/2020 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 12(T)/2020.

1. K Buoy, *Fl.G.5s*, in position 03°15'.19N, 113°02'.52E is missing.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 7332.

.....
89(T)*/2020 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 47(T)/2020.

1. Buoy No.11, *Fl.G.5s*, in position 03°15'.55N, 113°02'.57E is missing.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 7332.

.....
104(T)*/2020 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 56(T)/2020.

1. Buoy I, *Fl.G.5s*, in position 03°15'.24N, 113°02'.25E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7332.
-

130*/2020 MALAYSIA – Sarawak – Kuala Bintulu – Buoy.

Source: Sarawak Marine Department No. 74/2020.

1. Porthand Buoy Kuala Kemena, *Fl.R.4s*, in position 03°11'.36N, 113°01'.67E move to 03°11'.38N, 113°01'.66E is resumed in operation.
 2. Former Notice No. 256/2019(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected –MAL 7332.
-

131*/2020 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 75/2020.

1. Buoy I, *Fl.G.5s*, in position 03°15'.24N, 113°02'.25E move to 03°15'.24N, 113°02'.24E is resumed in operation.
 2. Former Notice No. 104/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected –MAL 7332.
-

132*/2020 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 78/2020.

1. Buoy K, *Fl.G.5s*, in position 03°15'.19N, 113°02'.52E move to 03°15'.14N, 113°02'.55E is resumed in operation.
 2. Former Notice No. 49/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected –MAL 7332.
-

133*/2020 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 77/2020.

1. Buoy No.11, *Fl.G.5s*, in position 03°15'.55N, 113°02'.57E move to 03°15'.51N, 113°02'.56E is resumed in operation.
 2. Former Notice No. 89/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected –MAL 7332.
-

211(T)*/2020 MALAYSIA – Sarawak – Kuala Bintulu – Buoy.

Source: Sarawak Marine Department No. 118(T)/2020.

1. Port Hand Buoy Kuala Kemena, *Fl.R.4s*, in position 03°11'.38N, 113°01'.66E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 7332.
-