

**108\*/2023      MALAYSIA – Sarawak – Pelabuhan Bintulu – Light Buoy.**

**Source: Sarawak Marine Department No. 86/2023(T).**

1. Bintulu Port Buoy No. 5, *Fl.G.5s*, in position 03°15'.82N, 113°01'.21E is restored to normal.
  2. Former Notice No. 85(T)\*/23 is cancelled.  
(WGS84)
  3. Charts affected – MAL 7332.
-