

47(T)*/2024 MALAYSIA – Sarawak – Kuala Rajang – Buoy.

Source: Sarawak Marine Department No. 27(T)/2024.

1. Wk Buoy, *Fl(2)10s*, in position 02°09'.48N, 111°04'.01E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 740.
-