

**38(T)\*/2024 MALAYSIA – Sarawak – Tanjung Baram – Buoy.**

**Source: Sarawak Marine Department No. 13(T)/2024.**

1. Starboard Hand Buoy No. 1, *Fl.G.4s*, in position 04°36'.35N, 113°55'.87E is missing
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 750.
-