

69*/2021 MALAYSIA – Sarawak – Tanjung Baram – Buoy.

Source: Sarawak Marine Department No. 32/2021.

1. Starboard Hand Buoy No. 1 *Fl.G.4s* 04° 36'.90N, 113° 55'.90E and Port Hand Buoy No. 2 *Fl.R.4s* 04° 37'.27N, 113° 56'.18E is resumed in operation.
 2. Former Notice No. 191/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 752.
-