

219(T)*/2021 MALAYSIA – Sarawak – Tg.Baram – Buoy.

Source: Sarawak Marine Department No. 180/2021(T).

1. Special Mark Buoy (A) *Fl.Y.5s*, in position 04°36'.28N, 113°54'.67E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS 84)
 3. Charts affected – MAL 752
-