

55*/2022 MALAYSIA – Sarawak – Kuala Baram – Buoy.

Source: Sarawak Marine Department No. 38/2022(T).

1. Port Hand Buoy No.2 *Fl.R.4s*, in position 04°37'.27N, 113°56'.18E is restored to normal.
 2. Former Notice No. 40(T)*/22 is cancelled.
(WGS84)
 3. Charts affected – MAL 752
-