

107*/2023 MALAYSIA – Sarawak – Tanjung Baram – Light Buoy.

Source: Sarawak Marine Department No. 92/2023.

1. Port Hand Buoy No. 2, *Fl.R.4s*, in position 04°37'.27N, 113°56'.18E is restored to normal and move 04°37'.31N, 113°56'.34E.
 2. Former Notice No. 54(T)*/23 is cancelled.
(WGS84)
 3. Charts affected – MAL 752.
-