

**40(T)\*/2023      MALAYSIA – Sarawak – Tanjung Baram – Buoy.**

**Source: Sarawak Marine Department No. 12(T)/2023.**

1. Starboard Hand Buoy No. 1, *Fl.G.4s*, in position 04°36'.90N, 113°55'.90E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 754.
-