

**54(T)\*/2023      MALAYSIA – Sarawak – Tanjung Baram – Buoy.**

**Source: Sarawak Marine Department No. 44(T)/2023.**

1. Port Hand Buoy No. 2, *Fl.R.4s*, in position 04°37'.27N, 113°56'.18E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 754.
-