

**106\*/2023      MALAYSIA – Sarawak – Tanjung Baram – Light Buoy.**

**Source: Sarawak Marine Department No. 91/2023.**

1. Starboard Hand Buoy No. 1, *Fl.G.4s*, in position 04°36'.90N, 113°55'.90E is restored to normal and move 04°36'.35N, 113°55'.87E.
  2. Former Notice No. 40(T)\*/23 is cancelled.  
(WGS84)
  3. Charts affected – MAL 754.
-