

76(T)*/2021 MALAYSIA – Sabah – Terusan Tando Bulong – Beacons.

Source: Royal Malaysian Navy.

1. Beacon P6 and Beacon S5, in position 04°24'.76N, 118°35'.68E and 04°24'.59N, 118°36'.01E is unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 8433.
-