

79(T)*/2021 MALAYSIA – Sabah – Terusan Tando Bulong – Buoy.

Source: Royal Malaysian Navy.

1. Buoy *Fl.10s*, in position 04°23'.48N, 118°36'.27E is unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 8433.

.....