

**86(T)\*/2023 MALAYSIA – Sabah – Terusan Tando Bulong – Beacons.**

**Source: Sabah Marine Department No. 12/2023(T).**

1. Temporary Beacons for Terusan Tando Bulong is damaged and unlit :

Beacon No 1, Fl.G.3s5m5M	04° 18'.12N,	118° 33'.18E
Beacon No 2, Fl.G.3s5m5M	04° 21'.45N,	118° 33'.50E
Beacon No 3	04° 21'.48N,	118° 34'.57E
Beacon No 4, Fl.R.5s5m5M	04° 22'.68N,	118° 34'.53E
Beacon No 5	04° 22'.62N,	118° 35'.55E
Beacon No 8, Fl.G.3s5m5M	04° 23'.05N,	118° 37'.13E
Beacon No 12, Fl.G.3s5m5M	04° 23'.72N,	118° 37'.87E
Beacon No 10	04° 23'.80N,	118° 37'.07E
Beacon No 29	04° 30'.48N,	118° 36'.43E

2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)

3. Charts affected – MAL 8433.

---