

83*/2023 MALAYSIA – Perak – Selat Manjung (Dinding) – Light Buoy.

Source: Marine Department of Malaysia No. 113/2023.

1. Selat 2R, *Fl.R.*3s, 04°15'.15N, 100°34'.73E and Selat 2G *Fl(2+1)G.*10s, 04°15'.03N, 100°34'.76E is restored to normal.
 2. Former Notice No. 127(T)*/19 and 179(T)*/21 is cancelled.
(WGS84)
 3. Charts affected – MAL 5416.
-