

179(T)*/2021 MALAYSIA – Perak – Selat Manjung (Dinding) – Light Buoy.

Source: Marine Department of Malaysia No. 157,161/2021(T).

1. Beting Light Buoy Q.G, 04°14'.12N, 100°34'.99E and Selat 2G *Fl(2+1)G.10s*, 04°15'.03N, 100°34'.76E are temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 5419

.....