176*/2021 MALAYSIA – Kedah – Pelabuhan Langkawi – Light Buoy.

Source: Marine Department of Malaysia No. 165/2021.

- 1. Jerkom 1 Light Buoy Fl.R.5s, in position 06°15'.31N, 099°45'.54E is restored to normal.
- 2. Former Notice No. 91/2014* is cancelled. (WGS84 DATUM)

3.	Charts	affected -	- MAL	5622.
٠.	0.14.60	anootoa		00

.....