

**70(T)\*/2024      MALAYSIA – Kelantan – Kuala Tok Bali – Light Buoys.**

**Source: Marine Department of Malaysia No. 59(T), 62(T)/2024.**

1. Tok Bali Port Limit Light Buoy No. 2, *Fl. Y. 10s*, in position 05°54'.10N, 102°32'.91E and Tok Bali 2G Light Buoy, *Fl(2)G. 6s*, in position 05°54'.73N, 102°29'.34E are unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 68.
- .....