

78(T)*/2021 MALAYSIA – Sabah – Terusan Tando Bulong – Beacon.

Source: Royal Malaysian Navy.

1. Beacon No.7, in position 04°22'.88N, 118°36'.27E is unlit.

2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

3. Charts affected – MAL 8434.

.....