



# MALAYSIAN NOTICES TO MARINERS

Monthly Edition 5 of 2014  
31 MAY 2014

## CONTENTS

- I - Explanatory Notes / Index of Charts Affected.
- II - Notices to Mariners and Corrections to Charts.
- III - Marine Safety Information.
- IV - Corrections to Malaysian List of Lights.

Mariners are requested to inform The Hydrographer, National Hydrographic Centre, Bandar Armada Putra, Pulau Indah, 42009 PORT KLANG, Selangor Darul Ehsan, Malaysia. (Tel: +603 3169 4400), (Fax: +603 3101 3111), E-mail: [nhc@hydro.gov.my](mailto:nhc@hydro.gov.my) immediately of the discovery of new dangers, changes or defects in aids to navigation and shortcoming in Malaysian charts or publications.

*DATO' PAHLAWAN ZAAIM BIN HASAN  
Rear Admiral  
The Hydrographer*



Your complimentary  
use period has ended.  
Thank you for using  
PDF Complete.

[Click Here to upgrade to  
Unlimited Pages and Expanded Features](#)

## SECTION I

### EXPLANATORY NOTES

Instructions for the correction of Malaysian Chart (MAL) while notices in Section III give information on marine safety information. Geographical positions refer to the largest scale chart unless otherwise stated. Bearing are true reckoned clockwise from 000 to 359, those relating to lights are from seaward.

Notices to Mariners correcting MAL charts are issued by the National Hydrographic Centre, Royal Malaysian Navy and should be inserted on the charts affected in waterproof violet ink in case of permanent notices and in pencil in case of temporary notices.

#### Temporary and Preliminary Notices

These are indicated by (T) or (P) after the notice number.

#### Original Information

An asterisk (\*) adjacent to the number of a notice indicates that the notice is based on original information.

#### Malaysian Notice (MN)

Mariners are to take note the legend MN indicates Malaysian Notice.

INDEX OF CHARTS AFFECTED			
MAL 4508	80/2014	MAL 5416	81/2014
MAL 5	83/2014, 84/2014, 86/2014(T), 87/2014(T)	MAL 6	83/2014, 85/2014(T)
MAL 521	82/2014, 86/2014(T)	MAL 68	84/2014, 87/2014(T)
MAL 5217	82/2014	MAL 865	85/2014(T)
MAL 54	86/2014(T)	MAL 872	85/2014(T)

ndoro - Lubang Island E, Tres Reyes Islands and

ice No. 1997/2014.

Click Here to upgrade to  
Unlimited Pages and Expanded Features

Chart MAL 4506 (Last Correction 38/2014) WGS 84 DATUM

**Insert** depth, 30, enclosed by 30m contour (a) 12° 32'.60N, 120° 38'.90E  
**Delete** depth, 66, close S of: (a) above

**81/2014\*** **Malaysia - Perak - Lumut - Sungai Manjung - Wreck.**

**Source: National Hydrographic Centre, Royal Malaysian Navy.**

Chart MAL 5416 (Last Correction 181/2013) WGS 84 DATUM

**Insert**  04° 14'.31N, 100° 38'.27E

**82/2014\*** **Malaysia - Melaka - Sungai Udang - Obstruction.**

**Source: National Hydrographic Centre, Royal Malaysian Navy.**

Chart MAL 521 (Last Correction 162/2013) WGS 84 DATUM

**Insert**  *Obstn* 02° 10'.35N, 102° 12'.14E

Chart MAL 5217 (Last Correction 161/2013) WGS 84 DATUM

**Insert**  *Obstn* 02° 10'.35N, 102° 12'.14E


**83/2014** **South China Sea - Pulau-Pulau Natuna Utara W and Central Luconia Gas Field - Platform.**

**Source: British Admiralty Notice No. 2079/2014.**

Chart MAL 5 (Last Correction 64/2014) WGS 84 DATUM

**Insert**  Rep (2014) 04° 41'.70N, 107° 36'.70E

Chart MAL 6 (Last Correction 69/2014) WGS 84 DATUM

**Insert**  04° 22'.00N, 111° 38'.20E

**84/2014** **Malaysia - Thailand - Cakarawala Field (JDA) - Platforms.**

**Source: Marine Department Malaysia No. 41/2014.**

Chart MAL 5 (Last Correction 83/2014) WGS 84 DATUM

**Insert**  Cakarawala D 07° 13'.40N, 103° 05'.77E

 Bumi B 07° 11'.53N, 103° 15'.13E

- Muda B
- Jengka B

07° 15'.80N,	103° 16'.24E
07° 10'.07N,	103° 11'.09E
07° 09'.60N,	103° 02'.23E
07° 35'.20N,	103° 01'.67E
07° 27'.13N,	103° 16'.51E

Chart MAL 68 (Last Correction 64/2014) WGS 84 DATUM

- Insert**
- Cakarawala D
  - Bumi B
  - Bumi D
  - Suriya B
  - Bulan B
  - Muda B
  - Jengka B

07° 13'.40N,	103° 05'.77E
07° 11'.53N,	103° 15'.13E
07° 15'.80N,	103° 16'.24E
07° 10'.07N,	103° 11'.09E
07° 09'.60N,	103° 02'.23E
07° 35'.20N,	103° 01'.67E
07° 27'.13N,	103° 16'.51E

### SECTION III

#### MARINE SAFETY INFORMATION

##### Drilling Operation.

Malaysia No. 09/2014(T).

1. PETRONAS CARIGALI SDN. BHD. IS CURRENTLY CONDUCTING EXPLORATION DRILLING IN AREA OF KUKUSAN-1, OFFSHORE SABAH AT POSITION 06 01.95N 115 32.92E STARTING FROM 10 MAY UNTIL 10 JULY 2014.
2. DETAILS OF THE DRILLING RIG ARE AS FOLLOWS :
  - A. VESSEL : NAGA-1
3. MARINERS ARE ADVISED TO NAVIGATE WITH EXTRA CAUTION WHEN APPROACHING VICINITY AND REQUESTED TO KEEP CLEAR 2 NM RADIUS FROM THE DRILLING VESSEL.
4. CHARTS AFFECTED : MAL 6, MAL 865 AND MAL 872.

86/2014(T) **Malaysia - Melaka - Pole Installation Operation.**

**Source: Marine Department Malaysia No. 31/2014(T).**

1. THE TRANSMISSION POLE INSTALLATION IS CURRENTLY BEING CARRIED OUT FROM SSU PANTAI SIRING TO SSU PULAU BESAR, MELAKA WATERS, STRAIT OF MALACCA STARTED FROM 21 OCT 2013 UNTIL 15 AUG 2015. THE COORDINATES ARE AS FOLLOWS:
  - A. T1 : 02 06.94N 102 20.06E
  - B. T2 : 02 06.95N 102 20.07E
  - C. T3 : 02 07.10N 102 20.22E
  - D. T4 : 02 07.36N 102 20.38E
  - E. T5 : 02 07.49N 102 20.70E
  - F. T6 : 02 07.62N 102 20.86E
  - G. T7 : 02 07.75N 102 21.01E
  - H. T8 : 02 07.88N 102 21.17E
  - I. T9 : 02 07.97N 102 21.28E
  - J. T10 : 02 08.09N 102 21.45E
  - K. T11 : 02 08.20N 102 21.62E
  - L. T12 : 02 08.30N 102 21.76E
2. THE VESSELS INVOLVED ARE AS FOLLOWS:
  - A. KETARA LIMA
  - B. KETARA ENAM
  - C. KETARA LAPAN
  - D. KETARA SEMBILAN
  - E. KETARA BEAUTIFUL 2
  - F. KETARA TUG 2
3. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN IN THE VICINITY AND KEEP CLEAR OF THE WORKING AREA.
4. CHARTS AFFECTED : MAL 5, MAL 54 AND MAL 521.



Your complimentary  
use period has ended.  
Thank you for using  
PDF Complete.

[Click Here to upgrade to  
Unlimited Pages and Expanded Features](#)

**Offshore - Drilling Operation.**

**Malaysia No. 39/2014(T).**

WILL BE CARRIED IN AREA OF KAMANJU-1, SOUTH CHINA  
SE STARTING FROM 13 MAY UNTIL 30 JUNE 2014.

2. DETAILS OF THE DRILLING RIG ARE AS FOLLOWS :
  - A. DRILLING RIG : TRIDENT IX
3. MARINERS ARE REQUESTED TO KEEP CLEAR OF THE SURVEY AREA WITH MINIMAL DISTANCE OF 2 KM RADIUS FROM THE DRILLING AREA.
4. CHARTS AFFECTED : MAL 5 AND MAL 68.  
.....



*Your complimentary  
use period has ended.  
Thank you for using  
PDF Complete.*

[Click Here to upgrade to  
Unlimited Pages and Expanded Features](#)

#### SECTION IV

#### CORRECTIONS TO MALAYSIAN LIST OF LIGHTS

-NIL-