

180(T)*/2021 MALAYSIA – Perak – Selat Manjung (dinding) – Light Beacon.

Source: Marine Department of Malaysia No. 158,159/2021(T).

1. Muroh Light Beacon Fl.R.11m5M, 04°13'.33N, 100°35'.10E and Llyod Q.R.10m8M, 04°15'.43N, 100°35'.09E are temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5416
-