155(T)*/2021 MALAYSIA – Pahang – Kuala Kuantan – Light buoy.

Source: Marine Department of Malaysia No. 150/2021(T).

- 1. Sungai Kuantan Wreck Bouy FL. YG5s, in position 03°47'.45N, 103°21'.16E is destroyed.
- 2. Mariners are advised to navigate with caution in the area. (WGS84 DATUM)
- 3. Charts affected MAL 6359

.....