


MAL 6522


36*/2019 MALAYSIA – Terengganu – Kg. Pantai Batu Buruk – Submarine cable. Legend

Source: National Hydrographic Centre.

Chart MAL 6522 (Last Correction 144/2010) WGS 84 DATUM

Insert submarine cable,  , joining: 05° 18'.71N 103° 10'.00E(E border)
05° 18'.76N 103° 09'.67E(shore)

legend, *Kuala Dungun – Kuala Terengganu*,
centred on: 05° 18'.73N 103° 09'.88E

submarine cable,  , joining: 05° 18'.76N 103° 09'.67E(shore)
05° 19'.03N 103° 10'.00E(E border)

legend, *Kuala Terengganu – Kuala Besut*,
centred on: 05° 18'.90N 103° 09'.84E

199*/2019 MALAYSIA – Terengganu – Kuala Terengganu – Buoy.

Source: Marine Department of Malaysia No. 141/2019.

Chart MAL 6522 (Last Correction 36/2019) WGS 84 DATUM

Delete  *LFl.10s* 05° 21'.38N, 103° 09'.60E

268*/2019 MALAYSIA – Terengganu – Kuala Terengganu – Buoy.

Source: Marine Department of Malaysia No. 193/2019.

Chart MAL 6522 (Last Correction 199/2019) WGS 84 DATUM

Insert  *LFl.10s* 05° 21'.40N, 103° 09'.70E

125*/2020 MALAYSIA – Terengganu – Kuala Terengganu – Cultural Features.

Source: National Hydrographic Centre.

Chart MAL 6522 (Last Correction 268/2019) WGS 84 DATUM

Insert legend, 12.411 05° 20'.40N, 103° 08'.72E

170(T)*/2020 MALAYSIA – Terengganu – Pulau Pasir – Light Bouy.

Source: Marine Department of Malaysia No. 211/2020(T).

1. Light Buoy *Fl(4)G.10s*, in position 05°19'.63N, 103°07'.83E is temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 6522.
-

29*/2021 MALAYSIA – Terengganu – Kuala Terengganu – Wreck.

Source: Marine Department of Malaysia No. 07/2021.

Chart MAL 6522 (Last Correction 170/2020) WGS 84 DATUM

Insert  *Setia Kilas* 05° 20'.52N, 103° 09'.25E

44*/2021 MALAYSIA – Terengganu – Pulau Pasir – Light buoy.

Source: Marine Department of Malaysia No. 51/2021.

Chart MAL 6522 (Last Correction 29/2021) WGS 84 DATUM

Move  *Kuala Terengganu 3G* from: 05° 19'.92N, 103° 07'.78E
Fl.G.2s to: 05° 20'.01N, 103° 07'.76E
