

70(T)*/2024 MALAYSIA – Kelantan – Kuala Tok Bali – Light Buoys.

Source: Marine Department of Malaysia No. 59(T), 62(T)/2024.

1. Tok Bali Port Limit Light Buoy No. 2, *Fl.Y.10s*, in position 05°54'.10N, 102°32'.91E and Tok Bali 2G Light Buoy, *Fl(2)G.6s*, in position 05°54'.73N, 102°29'.34E are unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 6603.
-