122*/2022 MALAYSIA – Johor – Tg. Piai – Buoy.

Source: Marine Department of Malaysia No. 124/2022.

- 1. Piai Special Mark, Fl. Y.5s, in position 01°14'.28N, 103°29'.73E is restored to normal.
- 2. Former Notice No. 108(T)*/22 is cancelled. (WGS84)
- 3. Chart affected MAL 521