

46*/2023 MALAYSIA – Johor – Muar – Port Limit.

Source: HIS MAJESTY'S GOVERNMENT GAZETTE.

Chart MAL 521 (Last Correction 166/2022) WGS 84 DATUM

Insert	port limit, pecked line joining	(1)	02° 06'.30N	102° 29'.50E
		(2)	01° 58'.70N	102° 23'.30E
		(3)	01° 49'.40N	102° 40'.80E
		(4)	01° 51'.30N	102° 42'.70E
	legend, ' <i>Batas Pelabuhan Muar / Muar Harbour Limit</i> ' centred on		01° 55'.40N, 102° 30'.00E	
Delete	port limit, pecked line joining	(1)	02° 05'.88N	102° 29'.16E
		(2)	02° 00'.55N	102° 24'.68E
		(3)	01° 55'.56N	103° 31'.47E
		(4)	01° 59'.65N	102° 34'.97E
	legend, ' <i>Batas Pelabuhan Muar / Muar Harbour Limit</i> ' centred on		01° 58'.10N,	102° 28'.15E

.....