

97(T)*/2022 MALAYSIA – Selangor – Kuala Selat Lumut – Lightbouy.

Source: Marine Department of Malaysia No. 87(T)/2022.

1. Terusan Lightbouy *Fl.R. 10s*, in position 02°51'.48N, 101°15'.35E is off station.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5255.
-