

MAL 58

44/2004* **Indonesia – Sumatera – Malacca Strait – T. Langsa – Light**

Source : British Admiralty Notice No : 400/2004

Chart MAL 58 (Last Correction 118/2003) KERTAU (1948) DATUM

Amend	light to, Q.8m 10M	04° 33. 5N,	098° 04'. 4E
--------------	-----------------------	-------------	--------------

45/2004* **Indonesia – Sumatera – East Coast – Malacca Strait – P. Jarak Southwestwards and Northwestwards – T. Bedukang Eastwards – Depths**

Source: British Admiralty Notice No. 402/2004

Chart MAL 58 (Last Correction 44/2004) KERTAU (1984) DATUM

Insert	depth <i>42</i> enclose by 50m approximate contour	04° 11. 5N,	099° 49'. 6E
	depth <i>35</i> and extend 50m approximate contour NW. to enclose	03° 51. 1N,	099° 42'. 8E
	depth <i>46</i> enclose by 50m approximate contour	03° 53. 8N,	099° 58'. 0E

66/2004* **Malacca Strait – Peninsular Malaysia West Coast – Kuala Kedah – Beacons**

Source : Marine Dept. Peninsular Malaysia Notice No 7/04

Chart MAL 58 (Last Correction 45/2004) KERTAU (1948) DATUM

Insert	 Q G. 5M	06° 05. 80N,	100° 16'. 20E
	 Q R. 5M	06° 05. 20N,	100° 14'. 20E

78/2004* **Indonesia – Sumatera – Ujung Peureulak South – south – eastwards – Kuala Beukah Oil Terminal – Light**

Source: British Admiralty Notice No : 2157/2004

Chart MAL 58 (Last Correction 66/2004) KERTAU (1948) DATUM

Amend	light to, Fl (2) 10s 13M	04° 51. 6N,	097° 54'. 7E
--------------	--------------------------	-------------	--------------

89/2004* **Thailand – West Coast – Kantang Southwards – Ko Sukon North – westwards – Buoy**

Source : British Admiralty Notice No : 2704/04

Chart MAL 58 (Last Correction 78/2004) REVISED KERTAU DATUM

Insert	safe water can light - buoy with spherical top mark, <i>Fl.</i> 6s	07° 07. 9N,	099° 32'. 7
---------------	--	-------------	-------------

90/2004* Malaysia – Peninsular Malaysia, West Coast – Pulau Pangkor North – westwards – Obstruction

Source: British Admiralty Notice No : 2676/04

Chart MAL 58 (Last Correction 89/2004) REVISED KERTAU DATUM

Insert

52

Obstn

04° 30. 3N,

099° 56'. 3E

55/2005*

Malacca Strait – Ujung Peureula Eastwards – Wreck.

Source: British Admiralty Notice No. 1379/2005.

Chart MAL 58 (Last Correction NE AUG 04) WGS 84 DATUM

Substitute

++ PA

for

35

Wk

05° 00'. 0N,

099° 00'. 0E

64/2006*

Malacca Strait – Pulau Pinang South –westwards – Wreck.

Source: British Admiralty Notices No: 1866/2006.

Chart MAL 58 (Last Correction 55/2005) WGS 84 DATUM

Insert

45

Wk

04° 50'.30N,

099° 41'.70E

150/2006*

Thailand – West Coast – Ko Tarutao South–eastwards – Selat Cincin – Wrecks.

Source : British Admiralty Notices No: 5678/2006.

Chart MAL 58 (Last Correction 55/2005) WGS 84 DATUM

Insert

++

(a)

06° 31'. 79N,

099° 48'. 66E

Delete

10s

Wk, adjacent to :

a) above

79/2007*

Malacca Strait – Sumatera Eastwards – Tanjung Bedukang Eastwards – Obstruction.

Source: British Admiralty Notices No. 2809/2007.

Chart MAL 58 (Last Correction 150/2006) WGS 84 DATUM

Delete



Obstn PA Rep (1981)

04° 09'. 00N,

99° 12'. 00N,

69/2008* Malaysia – Peninsular Malaysia, West Coast – Pulau Langkawi – Kuala Kedah – Light Buoy.

Source: Peninsular Malaysia Marine Department Notice No. 14/2008.

Chart MAL 58 (Last Correction 79/2007) WGS 84 DATUM

Insert	 <i>Fl.Y.10s</i> <i>Enggang 1Y</i>	06° 14'. 2N,	099° 53'. 4E
Insert	 <i>Fl(4)Y.10s</i> <i>Enggang 2Y</i>	06° 15'. 0N,	099° 53'. 5E
Insert	 <i>Fl.Y.10s</i> <i>Kuala Kedah 1Y</i>	06° 05'. 48N,	100° 14'. 63E
Insert	 <i>Fl(4)Y.10s</i> <i>Kuala Kedah 2Y</i>	06° 04'. 88N,	100° 14'. 23E
Insert	 <i>Qk.W</i> <i>Aston</i>	05° 24'. 38N,	100° 20'. 68E

175/2008* Malacca Strait – Sumatera Eastwards – Pulau Pandang North – Eastwards – Wreck.

Source: Admiralty Notice No. 5166/2008.

Chart MAL 58 (Last Correction 69/2008) WGS 84 DATUM

Insert	 <i>PA</i>	3° 35'. 40N,	100° 00'. 80E
--------	---	--------------	---------------

176/2008* Malacca Strait – Peninsular Malaysia West Coast – Kuala Jerlun – Light Beacon.

Source: Marine Dept. Peninsular Malaysia Notice No 62/2008

Chart MAL 58 (Last Correction 175/2008) WGS 84 DATUM

Insert	 <i>Fl.G.3s10m5M</i>	06° 12'. 38N,	100° 14'. 00E
--------	---	---------------	---------------

209/2008* Thailand – West Coast – Approaches to Kantang – Ko Talibong Eastwards – Wreck.

Source : Admiralty Notice No. 6470/2008

Chart MAL 58 (Last Correction 176/2008) WGS 84 DATUM

Delete		07° 14'. 06N,	99° 28'. 04E
--------	---	---------------	--------------

73/2009* Thailand – West Coast – Ko Tarutao Eastwards and Pulau Langkawi Northwards – Reported Anchorages

Source: Admiralty Notice No. 1185/2009.

Chart MAL 58 (Last Correction 209/2008) WGS 84 DATUM

Delete		06° 32'. 13N,	099° 42'. 81E
		06° 27'. 93N,	099° 48'. 41E

103/2009* Malaysia – Peninsular Malaysia, West Coast – Pulau Jarak Westwards – Obstruction.

Source: British Admiralty Notices No. 2282/2009.

Chart MAL 58 (Last Correction 73/2009) WGS 84 DATUM

Insert

162/2009* **Malaysia – Malacca Strait – Wreck.**

Source : National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 58 (Last Correction 103/2009) WGS 84 DATUM

Insert

54/2010* Indonesia – Sumatera – East Coast – Approaches Teluk Aru Eastwards – Platform. Submarine Pipeline. Restricted Area.

Source: British Admiralty Notices No. 1115/2010.

Chart MAL 58 (Last Correction 162/2010) WGS 84 DATUM

Insert

129/2011*(T) Malaysia – Pulau Langkawi – Pulau Pinang – Light House Unlit.

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 58 (Last Correction 54/2010) WGS 84 DATUM

Insert

163/2011(T)* Malaysia – West Coast – Kepulauan Sembilan – Lighthouse Unlit.

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 58 (Last Correction 171/2007) WGS 84 DATUM

Insert

199/2011* **Malaysia – West Coast – Kepulauan Sembilan – Lighthouse.**

Source: Marine Department Peninsular Malaysia No. 80(T)/2011.

Chart MAL 58 (Last Correction 163/2011(T)) WGS 84 DATUM

Insert

40/2012* **Thailand – Ko Dok Mai – Islands.**

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 58 (Last Correction 199/2011) WGS 84 DATUM

Insert • (68)

07° 47'. 72N, 98° 32'. 07E

54/2012 **Thailand – West Coast – Ko Muk, Ko Talibong and Ko Sukon –Submarine power cables.**

Source: British Admiralty Notices No. 0495/2012.

Chart MAL 58 (Last Correction 40/2012) WGS 84 DATUM

Insert submarine power cable, joining:

07° 21'.70N,	99° 18'.20E(shore)
07° 20'.70N,	99° 22'.00E(shore)
and	
07° 16'.70N,	99° 23'.20E(shore)
07° 18'.10N,	99° 25'.20E
and	
07° 06'.80N,	99° 34'.90E(shore)
07° 07'.00N,	99° 35'.10E
07° 08'.50N,	99° 35'.30E
07° 08'.90N,	99° 35'.20E(shore)

59/2012(T)* Malaysia – West Coast – Tg. Katak – Light Beacon Unlit.

Source: National Hydrographic Centre, Royal Malaysian Navy

Chart MAL 58 (Last Correction 54/2012) WGS 84 DATUM

Insert legend (**unlit**) for
Pulau Katak Beacon, Fl.4s7M

04° 09'. 38N, 100° 37'. 18E

114/2012* Indonesia – Sumatera – East Coast – Permatang Deli – Wreck.

Source: National Hydrographic Centre, Royal Malaysia Navy.

Chart MAL 58 (Last Correction 59(T) /2012) WGS 84 DATUM

Delete

03°59'.69N, 098°51'.04E

Insert

03°50'.50N, 098°49'.16E

115/2012* **Malacca Strait – Sumatera, North-East Coast – Platform and Radar Beacon block.**

Source: National Hydrographic Centre, Royal Malaysia Navy.

Chart MAL 58 (Last Correction 114/2012) WGS 84 DATUM

Insert 

05°18'.96N, 098°03'.66E

the accompanying block, amendments to Platform and Radar beacon. Centre on:

05°44'.27N, 097°49'.97E

167/2012 **Indonesia – Sumatera – North East Coast – Approaches to Belawan– Light.**

Source: British Admiralty Notices No: 4908/2012.

Chart MAL 58 (Last Correction 199/2012) WGS 84 DATUM

Amend light-beacon to, FI(3)6s12M 03° 49'.79N, 098° 44'.14E

46/2013* **Indonesia – Sumatera – East Coast – Permatang Deli – Wreck.**

Source: Chart ID 10.

Chart MAL 58 (Last Correction 167/2012) WGS 84 DATUM

Insert  03° 57'.14N, 98° 52'.06E

98/2013(T)* **Malaysia – Kedah – Pulau Langkawi – Tg Chinchin – Light Beacon.**

Source: Royal Malaysian Navy.

Chart MAL 58 (Last Correction 46/2013) WGS 84 DATUM

Insert legend, (*Unlit*) for
FI(3)15s10M 06° 26'.29N, 099° 38'.75E

111/2013 **Malaysia – Kedah – Tg. Jaga – Wreck.**

Source: Marine Department Malaysia No. 55/2013.

Chart MAL 58 (Last Correction 98/2013(T)) WGS 84 DATUM

Insert  05° 45'.15N, 100° 14'.68E

177/2013(T) **Malaysia – Langkawi – Pulau Dangli – Light Beacon – Unlit.**

Source: Marine Department Malaysia No. 120/2013(T).

Chart MAL 58 (Last Correction 111/2013) WGS 84 DATUM

Insert legend, (*Unlit*) for
Beacon, FI.10s 06° 26'.85N, 099° 46'.58E

180/2013 **Malaysia – Perak – Sg Perak – Wreck.**

Source: Marine Department Malaysia No. 127/2013(T).

Chart MAL 58 (Last Correction 177/2013(T)) WGS 84 DATUM

Insert  PA 03° 55'.38N, 100° 40'.44E

92/2014 **Thailand - West Coast - Ko Phiphi Don S - Wreck.**

Source: British Admiralty Notices No. 2711/2014.

Chart MAL 58 (Last Correction 180/2013) WGS 84 DATUM

Insert



Rep(2014)

07° 41'.70N, 98° 46'.60E

114/2014(T)* **Malaysia - Kedah - Langkawi - Pulau Rebak Besar - Beacon Missing.**

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 58 (Last Correction 92/2014) WGS 84 DATUM

Insert

legend, (**Missing**) for
Beacon, Occ.R

06° 17'.55N, 099° 41'.35E

135/2014(T) **Malaysia - Kedah - Kuala Kedah - Light Beacon Unlit.**

Source: Marine Department Malaysia No. 82/2014(T).

Chart MAL 58 (Last Correction 114/2014(T)) WGS 84 DATUM

Insert

legend, (**Unlit**) for
Light Beacon, Q.R.5M

06° 05'.18N, 100° 14'.85E

39/2015 **Malacca Strait - Belawan NE - Depth.**

Source : British Admiralty Notices No: 38/2015.

Chart MAL 58 (Last Correction 135/14(T)) WGS 84 DATUM

Insert

depth, 19_i, and extend 30m contour N
to enclose

04° 13'.30N, 099° 21'.70E

41/2015* **Malaysia - Perak - Pulau Jarak - Obstruction.**

Source: Royal Malaysia Navy.

Chart MAL 58 (Last Correction 39/2015) WGS 84 DATUM

Insert



Rep (2015)

03° 57'.79N, 100° 06'.80E

57/2015 **Corrigendum Notices to Mariners 2 of 2015.**

Amend Notices No. 39/2015

Chart MAL 58 (Last Correction 41/2015) WGS 84 DATUM

Insert

depth, 19_i , enclosed by 20m contour

04° 13'.3N, 099° 21'.7E

58/2015 **INDONESIA - Sumatera - Teluk Aru - Sembilan E - Depth.**

Source: British Admiralty Notices No. 1097/2015.

Chart MAL 58 (Last Correction 57/2015) WGS 84 DATUM

Insert depth, 36 04° 10'.5N, 098° 23'.7E

118/2015 **INDONESIA – Sumatera – Approaches to Belawan – Wreck.**

Source: British Admiralty Notice No. 2758/2015.

Chart MAL 58 (Last Correction 58/2015) WGS 84 DATUM

Insert  03° 53'.9N, 98° 45'.2E

145/2015 **INDONESIA – Sumatera – Approaches To Belawan – Wreck.**

Source: British Admiralty Notice No. 3442/15.

Chart MAL 58 (Last Correction 118/2015) WGS 84 DATUM

Insert  03° 53'.8N, 98° 45'.6E

27/2016(T)* **MALAYSIA – Perak – Pulau Jarak – Light Beacon.**

Source: Royal Malaysian Navy.

Chart MAL 58 (Last Correction 145/2015) WGS 84 DATUM

Insert legend, (Unlit) for
Pulau Jarak, FI(2)15s162m 20M 03° 58'.60N, 100° 06'.00E

30/2016* **MALAYSIA – Pulau Pinang – Pulau Jarak – Wreck.**

Source: National Hydrographic Centre.

Chart MAL 58 (Last Correction 27/2016) WGS 84 DATUM

Replace ++ PA for ++ 03° 58'.99N, 099° 50'.96E

60/2016* **MISCELLANEOUS UPDATES TO CHARTS**

Source: National Hydrographic Centre.

Chart MAL 58 (Last Correction 30/2016) WGS 84 DATUM

Insert Magenta limit and chart number,
5625, as follows: (a) 06° 21'.70N, 100° 04'.00E
 (b) 06° 25'.10N, 100° 04'.00E
 (c) 06° 25'.10N, 100° 09'.30E
 (d) 06° 21'.70N, 100° 09'.30E

75/2016 Malaysia – Pulau Langkawi – Kuala Kedah – Light Buoys.

Source: Marine Department of Malaysia No. 25, 29/2016.

Chart MAL 58 (Last Correction 60/2016) WGS 84 DATUM

Delete	 <i>Fl.Y.10s</i> <i>Enggang 1Y</i>	06° 14'. 20N, 099° 53'. 40E
	 <i>Fl(4)Y.10s</i> <i>Enggang 2Y</i>	06° 15'. 00N, 099° 53'. 50E
	 <i>Fl.Y.10s</i> <i>Kuala Kedah 1Y</i>	06° 05'. 50N, 100° 14'. 70E
	 <i>Fl(4)Y.10s</i> <i>Kuala Kedah 2Y</i>	06° 04'. 90N, 100° 14'. 30E

30/2017*(T) MALAYSIA – Kedah – Kuala Kedah – Light beacon.

Source: Marine Department of Malaysia No. 4/2017(T).

Chart MAL 58 (Last Correction 75/2016) WGS 84 DATUM

Insert	legend (Ru) for Kuala Kedah Water Light beacon No.2R, QR.5M	06°05'.19N, 100°14'.84E
Delete	QR.5M	(above)

51*/2018 MALAYSIA – Perak – Pulau Pangkor – Anchorage area.

Source: Marine Department of Malaysia No. 15/2018.

Chart MAL 58 (Last Correction 30/2017) WGS 84 DATUM

Insert	limit of anchorage area, pecked line, joining:	(a)	04° 10'.50N, 100° 29'.50E
		(b)	04° 10'.50N, 100° 32'.00E
		(c)	04° 07'.50N, 100° 29'.50E
		(d)	04° 07'.50N, 100° 32'.00E

254*/2018 MALAYSIA – Perak – SE P. Jarak – Wreck.

Source: KD MAHAWANGSA, Royal Malaysian Navy.

Chart MAL 58 (Last Correction 51/2018) WGS 84 DATUM

Insert PA 03° 51'.56N, 100° 14'.18E

282*/2018 MALAYSIA – Perak – SE Tg. Katak – Wreck.

Source: National Hydrographic centre.

Chart MAL 58 (Last Correction 254/2018) WGS 84 DATUM

Insert  *REP* (2018)
PA 04° 07'.58N, 100° 38'.91E

103(T)*/2019 MALAYSIA – Pulau Pinang – North Channel – Light buoy.

Source: Marine Department of Malaysia No. 56(T)/2019.

1. Penang No.1G, *Fl.G.4s* in position 05°34'.93N, 100°13'.53E is off station.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 58.

104(T)*/2019 MALAYSIA – Pulau Pinang – Muka Head – Lighthouse.

Source: Marine Department of Malaysia No. 59(T)/2019.

1. Muka Head lighthouse, FI.10s242m25M, in position 05°28'.34N, 100°10'.83E is temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 58.

33(T)*/2020 MALAYSIA – Pulau Pinang – Muka Head – Lighthouse.

Source: Marine Department of Malaysia No. 05(T)/2020.

1. Muka Head lighthouse, in position 05°28'.34N, 100°10'.82E is temporarily operating on reduced power and light nominal range is reduced to 10M.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 58.
-

55/2020 INDONESIA – Sumatera – Moored storage tanker. Platform.

Source: British Admiralty Notice No. 1563/20.

Chart MAL 58 (Last Correction 33/2020) WGS 84 DATUM

Delete		Langsa Venture	05° 18'.92N,	098° 02'.73E
			05° 18'.96N,	098° 03'.66E

148*/2020 MALAYSIA – Selangor – SW Sabak Bernam – Wreck.

Source: Marine Department of Malaysia No. 192(T)/2020.

Chart MAL 58 (Last Correction 55/2020) WGS 84 DATUM

Insert		PA	03° 36'.31N,	100° 29'.82E
--------	---	----	--------------	--------------

185*/2020 MALAYSIA – Pulau Pinang – SW Pu. Kendi – Obstruction.

Source: Marine Department of Malaysia No. 270/2020.

Chart MAL 58 (Last Correction 148/2020) WGS 84 DATUM

Insert		Obstn	05° 13'.50N,	100° 09'.75E
--------	---	-------	--------------	--------------

39*/2021 MALAYSIA – Perak – Sg. Tiang – Beacon.

Source: Marine Department of Malaysia No. 41,44/2021.

Chart MAL 58 (Last Correction 185/2020) WGS 84 DATUM

Insert		Fl.R.5s	03° 54'.10N,	100° 42'.06E
Delete		Fl.5s8M	03° 54'.33N,	100° 42'.28E
