

104*/2023 MALAYSIA – Johor – Pengerang – Buoy.

Source: Marine Department of Malaysia No. 124/2023.

1. Buoy, *Fl(2)10s*, in position 01°17'.68N, 104°11'.09E is restored to normal.
 2. Former Notice No. 55(T)*/23 is cancelled.
(WGS84)
 3. Charts affected – MAL 6147.
-