

127(T)*/2021 MALAYSIA – Pahang – Pulau Tioman – Light Beacon.

Source: Marine Department of Malaysia No. 112/2021(T).

1. Light Beacon Q.G.3.5m5M, in position 02°49'.13N, 104°09'.38E is temporarily unlit.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 6257.
-