

MAL 6400

84*/2019 MALAYSIA – Pahang – Sg. Balok – Light beacon.

Source: Marine Department of Malaysia No. 73/2015.

Chart MAL 6400 (Last Correction NC/2018) WGS 84 DATUM

Delete  Q.8m4M 03° 56'.26N, 103° 22'.57E

101*/2019 MALAYSIA – Pahang – Pelabuhan Kuantan – Blocks.

Source: National Hydrographic Centre.

Chart MAL 6400 (Last Correction 84/2019) WGS 84 DATUM

Insert the accompanying block, centred on: (a) 03° 59'.48N, 103° 26'.22E
(b) 03° 40'.00N, 103° 21'.00E

198*/2019 MALAYSIA – Pahang – Pelabuhan Kuantan – Light beacon.

Source: Marine Department of Malaysia No. 150(T)/2019.

Chart MAL 6400 (Last Correction 101/2019) WGS 84 DATUM

Insert legend, (Ru) 03° 57'.57N, 103° 27'.44E

221*/2019 MALAYSIA – Pahang – Pelabuhan Kuantan – Depths.Contours.

Source: National Hydrographic Centre.

Chart MAL 6400 (Last Correction 198/2019) WGS 84 DATUM

Delete depth, 15₄, enclosed by 20m contour 03° 59'.42N, 103° 25'.75E
depth, 15, and associated 20m contour SE to enclose 03° 59'.17N, 103° 25'.82E

70(T)*/2020 MALAYSIA – Pahang – Tg. Gelang – Light beacon.

Source: Marine Department of Malaysia No. 59(T)/2020.

1. Kuantan Port No.1 light beacon, Fl.G.5s15m8M, in position 03°56'.36N, 103°31'.74E is temporarily unlit.

2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

3. Charts affected – MAL 6400.

76*/2020 MALAYSIA – Pahang – Tg. Gelang – Light beacon.

Source: Marine Department of Malaysia No. 67/2020.

1. Kuantan Port No.1 light beacon, Fl.G.5s15m8M, in position 03°56'.36N, 103°31'.74E is restored to normal.
 2. Former Notice No. 70/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 6400.
-

110(T)*/2020 MALAYSIA – Pahang – Pelabuhan Kertih – Light buoy.

Source: Marine Department of Malaysia No. 120(T)/2020.

1. Rico Wreck light buoy, Fl(2)5s6M, in position 03°57'.81N, 103°27'.31E is temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected– MAL 6400.
-

129*/2020 MALAYSIA – Pahang – Pelabuhan Kuantan – Light buoy.

Source: Marine Department of Malaysia No. 140/2020.

1. Rico Wreck light buoy, Fl(2)5s6M, in position 03°57'.81N, 103°27'.31E is restored to normal.
 2. Former Notice No. 110/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected –MAL 6400.
-

149*/2020 MALAYSIA – Pahang – Pelabuhan Kuantan – Blocks.

Source: National Hydrographic Centre.

Chart MAL 6400 (Last Correction 129/2020) WGS 84 DATUM

Insert the accompanying block, centred on: 03°58'.30N, 103°26'.00E

187*/2020 MALAYSIA – Pahang – S Tg. Gelang – Wreck.

Source: Marine Department of Malaysia No. 256/2020.

Chart MAL 6400 (Last Correction 149/2020) WGS 84 DATUM

Insert  *Surya Nawa 2* 03° 53'.40N, 103° 25'.63E

196(T)*/2020 MALAYSIA – Pahang – Pelabuhan Kuantan – Light Bouy.

Source: Marine Department of Malaysia No. 285/2020(T).

1. Inner Light Buoy *LFl. 10s*, in position 03°55'.52N, 103°29'.15E is temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 6400.
-

206*/2020 MALAYSIA – Pahang – Tg. Gelang – Buoy.

Source: Marine Department of Malaysia No. 228/2020.

Chart MAL 6400 (Last Correction 196/2020) WGS 84 DATUM

Amend light-buoy to, *Fl(2)10s* 03° 57'.81N, 103° 27'.31E

207*/2020 MALAYSIA – Pahang – S Tg. Gelang – Wreck.

Source: Marine Department of Malaysia No. 294/2020.

Chart MAL 6400 (Last Correction 206/2020) WGS 84 DATUM

Insert  *Surya Nawa 2* 03° 52'.67N, 103° 24'.44E

Delete  *Surya Nawa 2* 03° 53'.40N, 103° 25'.63E

209*/2020 MALAYSIA – Pahang – Pelabuhan Kuantan – Light Buoy.

Source: Marine Department of Malaysia No. 302/2020.

1. Inner Light Buoy *LFl. 10s*, in position 03°55'.52N, 103°29'.15E is restored to normal.
 2. Former Notice No. 196/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 6400.
-

42*/2021 MALAYSIA – Pahang – Sungai Kuantan – Beacon.

Source: Marine Department of Malaysia No. 32/2021.

Chart MAL 6400 (Last Correction 209/2020) WGS 84 DATUM

Delete



Fl.G.2s10M

03° 48'.58N, 103° 20'.42E
