

MAL 654

98/2008*

Malaysia – Peninsular Malaysia – East Coast – Wreck.

Source : Peninsular Malaysia Marine Department No. 20(T)/2008.

Chart MAL 654 (Last Correction 103/2006) WGS 84 DATUM

Insert



05° 28'. 8N, 104° 03'. 4E

182/2008*

Malaysia – Peninsular Malaysia – East Coast – Pulau Perhentian Kecil – Under Water Pipe Line.

Source : Peninsular Malaysia Marine Dept. No: 64/2008.

Chart MAL 654 (Last Correction 98/2008) WGS 84 DATUM

Insert

Under water pipeline —•—•—• joining

a) 05° 51'. 24N, 102° 40'. 24E
b) 05° 51'. 60N, 102° 40'. 64E
c) 05° 51'. 90N, 102° 41'. 11E

200/2008*

Malaysia – Peninsular Malaysia – East Coast – Kuala Sungai Terengganu – Light Beacon.

Source : Peninsular Malaysia Marine Department Notices No. 68/2008.

Chart MAL 654 (Last Correction 182/2008) WGS 84 DATUM

Delete



Q.12m8M

05° 20'. 31N, 103° 08'. 51E

226/2008*

Malaysia – Peninsular Malaysia, East Coast – Kuantan Terengganu Northwards – Depths.

Source : British Admiralty Notice No. 6640/2008.

Chart MAL 654 (Last Correction 200/2008) WGS 84 DATUM

Substitute

depth 67 for depth 87

05° 21'.75N, 103° 08'.60E

147/2009*

Malaysia – Peninsular Malaysia – East Coast – Wreck.

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 654 (Last Correction 226/2008) WGS 84 DATUM

Substitute



WK PA for



05° 28'. 80N, 104° 03'. 40E

75/2010* Malaysia – Terengganu East Coast – Pulau Yu Besar – Pulau Yu Kecil – Restricted Area.

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 654 (Last Correction 147/2009) WGS 84 DATUM

Insert the accompanying block, amendment to
Restricted Area. Centred on: 05° 38'.02N, 103° 09'.50E

126/2010* Malaysia – Peninsular Malaysia, East Coast – Tok Bali, Pulau Cipu, Pulau Ling, Batuan Rusa Utara, Pulau Tokong Batu Kemudi and Batuan Tokong Dayak – Light Beacon.

Source: Marine Department Peninsular Malaysia No. 66/2010.

Chart MAL 654 (Last Correction 75/2010) WGS 84 DATUM

Insert  Fl.5s31m10M 05° 40'.62N, 102° 49'.51E
 Fl(2)6s13m5M 05° 44'.21N, 103° 01'.15E
 Fl(2)5s13m10M 05° 34'.32N, 102° 59'.10E
 Fl.6s16m10M 04° 52'.02N, 103° 39'.55E
 Fl.3s23m10M 04° 46'.94N, 103° 41'.33E

127/2010* Malaysia – Peninsular Malaysia – East Coast – Kuala Sungai Terengganu – Chart Limit.

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 654 (Last Correction 75/2010) WGS 84 DATUM

Insert the accompanying block, amendment to
chart limit. Centred on: 05° 20'.30N, 103° 07'.67E

184/2011(T)* Malaysia – East Coast –Tanjung Dungun – Light beacon Unlit.

Source: Marine Department Peninsular Malaysia Notice No. 71(T)/2011.

Chart MAL 654 (Last Correction 127/2010) WGS 84 DATUM

Insert legend (**Unlit**) for
Tg. Dungun Light beacon, Fl.10s20M 04° 47'.00N, 103° 26'.24E

80/2012 **Malaysia – East Coast – Tg. Dungun – Light Beacon – Resumed operations.**

Source: Marine Department Peninsular Malaysia Notice No. 14/2012.

Chart MAL 654 (Last Correction 184/2011(T)) WGS 84 DATUM

Insert Tg. Dungun Light beacon, Fl.10s69m20M
Notice No. 184/2011(T)* is hereby cancelled 04° 47'.00N, 103° 26'.24E

124/2012 **Malaysia – East Coast – Tg. Dungun – Light Beacon.**

Source: Marine Department Peninsular Malaysia Notice No. 31/2012 and 32/2012(T).

Chart MAL 654 (Last Correction 103/2012) WGS 84 DATUM

Amend range of light to, 10M

Insert legend (*Unlit*) for 04° 46'.90N, 103° 26'.28E

179/2012 **Malaysia – Terangganu – Pulau Redang – Wreck.**

Source: Department of Marine Park Malaysia 02 Nov 2012.

Chart MAL 654 (Last Correction 124/2012) WGS 84 DATUM

Insert  05° 43'.53N, 102° 57'.79E

27/2013 **Malaysia – East Coast – Tg. Dungun – Resumed Operation.**

Source: Marine Department Malaysia No. 06/2013.

Chart MAL 654 (Last Correction 179/2012) WGS 84 DATUM

Delete legend (*Unlit*) for
Fl.10s69m10M 04° 46'.90N, 103° 26'.28E
Notice No. 124/2012 is hereby cancelled

36/2013 **Malaysia – Terengganu – Kuala Setiu – Beacon.**

Source: Marine Department Malaysia No. 80/2012.

Chart MAL 654 (Last Correction 27/2013) WGS 84 DATUM

Delete  Fl.R.5s8m8M 05° 39'.84N, 102° 44'.67E

104/2013 **Malaysia – Terengganu – Penarik – Light Beacon.**

Source : Marine Department Malaysia No. 43/2013.

Chart MAL 654 (Last Correction 36/2013) WGS 84 DATUM

Insert  Fl (4).Y.10s12m8M 05° 36'.60N, 102° 49'.72E

120/2013 Malaysia - Terengganu - Kuala Terengganu - Lights.

Source: British Admiralty Notices No. 418/2008

Chart MAL 654 (Last Correction 104/2013) WGS 84 DATUM

Insert  Q.G.6M 05° 20'.48N, 103° 09'.26E

★ Q.R.6M 05° 20'.36N, 103° 09'.29E

201*/2017 MALAYSIA-CAMBODIA-THAILAND – Submarine Telecommunication Cable.

Source: Telekom Malaysia Berhad

Chart MAL 654 (Last Correction 120/2013) WGS 84 DATUM

Insert submarine telecommunication cable,
, joining:

04° 41'.99N	103° 56'.95E(W border)
04° 46'.08N	103° 57'.01E
04° 53'.05N	103° 55'.64E
04° 56'.90N	103° 54'.94E
04° 59'.04N	103° 52'.97E
05° 00'.97N	103° 52'.97E
05° 07'.76N	103° 47'.49E
05° 12'.28N	103° 44'.78E
05° 14'.97N	103° 42'.73E
05° 24'.08N	103° 38'.10E
05° 24'.60N	103° 36'.84E
05° 40'.35N	103° 26'.31E
05° 40'.59N	103° 25'.08E
05° 40'.98N	103° 24'.54E
05° 51'.98N	103° 18'.75E(N border)

73*/2018 Malaysia – Terengganu – Pulau Bidung – National Heritage. Legend. Note.

Source: Federal Government Gazette P.U (B) 60.

Chart MAL 654 (Last Correction 201/2017) WGS 84 DATUM

Insert limit of National Heritage area, , joining: (a)05° 37'.55N, 103° 02'.51E
(b)05° 36'.74N, 103° 03'.13E
(c)05° 36'.23N, 103° 02'.21E
(d)05° 37'.09N, 103° 01'.66E

legend, *Warisan Kebudayaan / National Heritage*, (*lihat Nota / see Note*), within: (a)-(d) above

the accompanying note, WARISAN KEBANGSAAN
/ NATIONAL HERITAGE, centred on: 04° 45'.54N, 103° 04'.12E

156*/2018 MALAYSIA – Terengganu – Dulang – Buoy.

Source: Marine Department of Malaysia No. 79(T)/2018.

Chart MAL 654 (Last Correction 73/2018) WGS 84 DATUM

Insert



Q.Y

05° 50'.62N, 104° 12'.51E

206(T)*/2018 MALAYSIA – Terengganu – Batuan Bara – Beacon.

Source: Marine Department of Malaysia No. 118(T)/2018.

1. Batuan Bara Beacon, Fl.4s, in position 05°38'.77N, 102°58'.28E is temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 654.

207(T)*/2018 MALAYSIA – Terengganu – Batuan Rusa – Beacon.

Source: Marine Department of Malaysia No. 117(T)/2018.

1. Batuan Rusa Beacon, Fl (2).5s, in position 05°34'.32N, 102°59'.10E is temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 654.

222*/2018 MALAYSIA – Terengganu – Oil Field Tapis – Platform.

Source: Vestigo Petroleum Sdn. Bhd.

Chart MAL 654 (Last Correction 207/2018) WGS 84 DATUM

Insert



TEMBIKAI

05° 13'.32N, 104° 26'.16E



CHENANG

05° 18'.12N, 104° 06'.42E

199*/2019 MALAYSIA – Terengganu – Kuala Terengganu – Buoy.

Source: Marine Department of Malaysia No. 141/2019.

Chart MAL 654 (Last Correction 222/2018) WGS 84 DATUM

Delete



LFI

05° 21'.38N, 103° 09'.60E

Insert



LFI.10s

05° 20'.40N, 103° 10'.30E

268*/2019 MALAYSIA – Terengganu – Kuala Terengganu – Buoy.

Source: Marine Department of Malaysia No. 193/2019.

Chart MAL 654 (Last Correction 199/2019) WGS 84 DATUM

Delete		<i>LFI.10s</i>	05° 20'.40N,	103° 10'.30E
---------------	---	----------------	--------------	--------------

31*/2020 MALAYSIA – Terengganu – Kuala Terengganu – Buoy.

Source: Marine Department of Malaysia No. 193/2019.

Chart MAL 654 (Last Correction 268/2019) WGS 84 DATUM

Insert		<i>LFI.10s</i>	05° 21'.40N,	103° 09'.70E
---------------	---	----------------	--------------	--------------

54*/2020 MALAYSIA – Terengganu – E P. Kapas – Platform. FPSO.

Source: Marine Department of Malaysia No. 33, 34/2020.

Chart MAL 654 (Last Correction 31/2020) WGS 84 DATUM

Insert		Jitang	05° 16'.82N,	104° 23'.11E
		FPSO MTC Ledang	05° 16'.97N,	104° 22'.97E

192(T)*/2020 MALAYSIA – Terengganu – Tg.Merang – Beacon.

Source: Marine Department of Malaysia No. 247/2020(T).

1. Beacon Fl(2)5s13m10M, in position 05°34'.32N, 102°59'.10E is temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 654.
-

30*/2021 MALAYSIA – Terengganu – Kg. Bari – Port Limit.

Source: JUPEM.BP.EP(S)10.18.2 Jld.140(74) Bth: 18 Dis 19.

Chart MAL 654 (Last Correction 192/2020) WGS 84 DATUM

Insert	port limit, pecked line joining	(a)	05° 34'.52N,	102° 52'.05E
		(b)	05° 34'.31N,	102° 52'.43E
		(c)	05° 33'.86N,	102° 52'.17E
		(d)	05° 34'.08N,	102° 51'.80E
			(a)-(d) close	
