

**109(T)\*/2022 MALAYSIA – Terengganu – P. Redang – Light Beacon.**

**Source: Marine Department of Malaysia No. 91/2022(T).**

1. Light Beacon Fl.10s132m10M, in position 05°44'.60N, 103°00'.20E is unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 664
-