

105*/2022 MALAYSIA – Sarawak – Tanjung Po – Buoys.

Source: Sarawak Marine Department No. 85/2022.

Chart MAL 7150 (Last Correction 78/2022) WGS 84 DATUM

Insert		NO. 9 Fl.G.5s.		01° 39'.41N, 110° 31'.39E
		NO. 10 Fl.R.5s.		01° 39'.26N, 110° 31'.68E
		NO. 11 Fl.G.5s.		01° 38'.99N, 110° 30'.46E
		NO. 12 Fl.R.5s.		01° 38'.72N, 110° 30'.64E
Move		NO. 5 Fl.G.5s.	from :	01° 42'.32N, 110° 33'.12E
			to :	01° 42'.33N, 110° 33'.04E
		NO. 6 Fl.R.5s.	from :	01° 42'.32N, 110° 33'.29E
			to :	01° 42'.31N, 110° 33'.37E
		NO. 7 Fl.G.5s.	from :	01° 41'.08N, 110° 32'.41E
			to :	01° 41'.14N, 110° 32'.35E
		NO. 8 Fl.R.5s.	from :	01° 40'.99N, 110° 32'.54E
			to :	01° 40'.95N, 110° 32'.60E

.....