

**189\*/2023 MALAYSIA – Sarawak – Tg. Similajau – Buoy.**

**Source: Sarawak Marine Department No. 149/2023.**

1. Racon buoy *Fl.5s*, in position 03°38'.04N, 113°15'.37E is restored to normal.
  2. Former Notice No. 189(T)\*/22 is cancelled.  
(WGS84)
  3. Chart affected – MAL 751.
-